

Preserve the Environment Without Sacrificing Quality

Quick Dry Rubberized Undercoating #4363-F



- Fast drying, easy to apply
- Paintable
- Excellent abrasion resistance
- Retains black color
- Won't sag or run
- Dries completely, yet remains flexible
- Seals out dust, fumes, heat and cold
- Aerosol package requires no clean-up
- 50 State & Canada compliant



TRANSTAR[®]
AUTOBODY TECHNOLOGIES, INC.

2040 Heiserman Drive
Brighton, MI 48114
ph (800) 824-2843
fax (800) 477-7923
www.tat-co.com

Quick Dry Rubberized Undercoating 4363-F

50 State Compliant

Quick Dry Rubberized Undercoat is a rapid-drying highly protective automotive coating for autobody interiors and underhood applications. Paintable. Resists rust and abrasion as it seals out dust and moisture. Deadens sound. Excellent adhesion to painted and unpainted surfaces. This product is 50 state compliant and meets all regulations for sale in the USA and Canada.

Application:

Shake well. Wash and solvent clean surface to remove all rust, dirt and grease using Aqua SCAT #6351/6354, Speedi SCAT #6321/6323, or SCAT #6311. For best results, use at room temperature (above 50°F). Hold can in an upright position and spray 8-10 inches from surface, apply using steady light strokes. Applying 2-3 light coats will produce a better finish than one heavy coat. Remove overspray with General Purpose Solvent #4074. May be topcoated after one hour. **NOTE:** *It is recommended that the material is sealed if painting over with a light color.*

Package:

#4363-F Quick Dry Rubberized Undercoat (50 State), 24 oz. aerosol, 6/case



Bajoprotector Ahulado de Secado Rápido 4363-F

Bajoprotector Ahulado de Secado Rápido es una capa altamente protectora de secado rápido para los interiores de los automóviles y aplicaciones bajo el cofre. Puede ser pintado. Resistente a la oxidación y la abrasión al interponer una barrera contra la tierra y la humedad. Ahoga el ruido. Excelente adhesión a superficies pintadas y sin pintar. Este producto es el estado 50 obediente y resuelve todas las regulaciones para la venta en los E.E.U.U. y el Canadá.

Aplicación:

Agítese bien. Lave y limpie el área con solventes para quitar el óxido, la suciedad y la grasa. Use Aqua SCAT (#6351/6354), Speedi SCAT (#6321/6323) o SCAT (#6311). Para mejores resultados, use a temperaturas no menores a 50°F. Agarre el bote en una posición vertical y manteniéndolo de 8 a 10 pulgadas de la superficie, aplique con movimientos firmes y ligeros. 2 a 3 varias capas delgadas producirán un mejor acabado que una capa gruesa. Quite el sobrero con el solvente de propósitos generales #4074. Puede ser capa pintura después de una hora. *Nota: Se recomienda que el material está sellado si esta pintando encima con un color claro.*

Tamaño del Envase:

4363-F Bajoprotector Ahulado de Secado Rápido
(Estado 50), 24 oz. Aerosol, 6 por cartón

Contact your local distributor at: